







Eva Creek

- Identified as a potential wind site after conducting a study to identify high wind area potential in our service area
- Sites were compared with existing transmission lines for close proximity
- Wind monitor installed, one year of data collected
- With favorable results, four more monitors were installed

Site Work

- Four to Five years of data good resource
- Some archeological work has been completed
- A system integration study was completed for worst case scenario
- With current grant money, a unit specific integration study is being conducted
- Some avian work has been completed

